



RELEASE NOTES

Product: **FW for MI 3309 (HW2.0/HW3.0)**

Version: **HW.1.271**

Release date: 06.07.2023

DESCRIPTION OF THE RELEASED PRODUCT:

FW for MI 3309 BT DeltaPAT/GT

DESCRIPTION OF CHANGES, DEPENDENCES AND HISTORY:

#	MI 3309						PC SW		
	FW version	Release date	Description of changes:	HW version	HD version	Metrel User Manual version	Metrel Electrical Safety Manager version	PATLink PRO	Release confirmed for following dealers
9	HW.1.271	06.07.2023	<ul style="list-style-type: none"> Support for GodexRT200 printer Removed language BUG fixes (BMC-80, BMC-84, BMC-85, BMC-87) (MPL-1045) 	HW3.0 HW2.0	HD4.0	Ver. 1.8.7 (ANG) Ver. 1.9.5 (UK) Ver. 1.10.4 (AUS-NZ)	V1.20.1.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	All supported.
8	HW.1.262	13.10.2022	<ul style="list-style-type: none"> Bug fix (ESP32 BT module, first initialization after FW upgrade fails) 	HW3.0 HW2.0	HD4.0	Ver. 1.8.7 (ANG) Ver. 1.9.5 (UK) Ver. 1.10.4 (AUS-NZ)	V1.19.0.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	All supported.
7	HW.1.260	23.09.2022	<ul style="list-style-type: none"> Bug fix (BT module Rayson BTM182, first initialization failed) 	HW3.0 HW2.0	HD4.0	Ver. 1.8.7 (ANG) Ver. 1.9.5 (UK) Ver. 1.10.4 (AUS-NZ)	V1.19.0.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	All supported.
6	HW.1.258	31.08.2022	<ul style="list-style-type: none"> Support for Wrover BT module BT version info under Instrument data 	HW3.0 HW2.0	HD4.0	Ver. 1.8.7 (ANG) Ver. 1.9.4 (UK) Ver. 1.10.4 (AUS-NZ)	V1.19.0.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	All supported.
5	HW.1.253	21.09.2021	<ul style="list-style-type: none"> Bug fix (Resetting of the instrument) 	HW3.0 HW2.0	/	Ver. 1.7.4 (ANG) Ver. 1.8.3 (UK) Ver. 1.9.3 (AUS-NZ)	V1.17.0.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	All supported.
4	HW.1.249	11.06.2021	<ul style="list-style-type: none"> Support for IT earthing system, (requirement of Norwegian market) 	HW3.0 HW2.0	/	Ver. 1.7.4 (ANG) Ver. 1.8.3 (UK) Ver. 1.9.3 (AUS-NZ)	V1.17.0.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	All supported.

			<ul style="list-style-type: none"> • Support for IET Code of practice 5th edition. (MPL-844) 						
3	HW.1.230	23.12.2020	<ul style="list-style-type: none"> • Extended Earth Continuity limits (0.01 Ohm) • Changed AutoSequences for NLD market (BMC-30) • Upgraded NLD translations • Bug fixes 	HW3.0 HW2.0	/	Ver. 1.6.3	V1.17.0.xxxx	V 2.0.5 (win7-10 /64bit) V 1.9.33 (win XP)	NLD (KWx)-(FW-246)
2	HW.1.224	20.01.2020	<ul style="list-style-type: none"> • Added Danish language 	HW3.0 HW2.0	/	Ver. 1.5.2	V1.15.0.xxxx	V 1.9.33 (win XP) V 2.0.1 (win7-10)	All supported.
1	HW.1.221	29.05.2019	<ul style="list-style-type: none"> • Corrected translation for labels printing (Slovakian, language) • Changed continuity limits for Dutch dealer settings (adjustment to new NEN3140 standard) • Changed message in initial settings (AUS, UK dealer) 	HW3.0 HW2.0	/	Ver. 1.5.2	V1.13.0.xxxx	V 1.9.33 (win XP) V 2.0.1 (win7-10)	All supported.

INSTALLATION PROCEDURE:

The instrument can be upgraded from a PC via the RS232 communication port. This enables to keep the instrument up to date even if the standards or regulations change. The firmware upgrade can be carried out with a help of special upgrading software – **FlashMe.exe** which will guide you through the upgrading procedure. Contact your local distributor for new versions of firmware.

COMPANY DATA:

METREL d.d.
Measuring and Regulation Equipment Manufacturer

Ljubljanska 77
SI-1354 Horjul

Tel: + 386 (0)1 75 58 200
Fax: + 386 (0)1 75 49 226
E-mail: metrel@metrel.si
<http://www.metrel.si>